

# What is the reason for temperature range limitation (0-70°C). Are you planning any developments for industrial scopes?

The temperature range is the result of the use of components (RAM, eMMC, CPU). We are not planning an industrial version. The URVEBoard A55 we are working on will have an industrial variant based on the RK3568 processor (equivalent to the 3566, but industrial).

---

Revision #2

Created 24 February 2023 08:41:27 by Sebastian Jarosz

Updated 24 February 2023 11:17:47 by Sebastian Jarosz